TwidoSuite V2.3 Getting Started

06/2011



35011385.06

The information provided in this documentation contains general descriptions and/or technical characteristics of the performance of the products contained herein. This documentation is not intended as a substitute for and is not to be used for determining suitability or reliability of these products for specific user applications. It is the duty of any such user or integrator to perform the appropriate and complete risk analysis, evaluation and testing of the products with respect to the relevant specific application or use thereof. Neither Schneider Electric nor any of its affiliates or subsidiaries shall be responsible or liable for misuse of the information contained herein. If you have any suggestions for improvements or amendments or have found errors in this publication, please notify us.

No part of this document may be reproduced in any form or by any means, electronic or mechanical, including photocopying, without express written permission of Schneider Electric.

All pertinent state, regional, and local safety regulations must be observed when installing and using this product. For reasons of safety and to help ensure compliance with documented system data, only the manufacturer should perform repairs to components.

When devices are used for applications with technical safety requirements, the relevant instructions must be followed.

Failure to use Schneider Electric software or approved software with our hardware products may result in injury, harm, or improper operating results.

Failure to observe this information can result in injury or equipment damage.

© 2011 Schneider Electric. All rights reserved.

Table of Contents



	Safety Information	5
	About the Book	7
Chapter 1	Installation and Program Start	9
•	System Requirements	10
	Installing and Uninstalling the Software	11
	Registering TwidoSuite	12
Chapter 2	Launching TwidoSuite	13
	Program Start	13
Chapter 3	Ungrading the Twido Eirmware	15
Chapter 5		15
0	Twido PLC Firmware Update	15
Chapter 4		17
	Main Window	18
	Setting Preferences	22
Chapter 5	Creating and Editing a Program	25
	Step 1: Create a New Project	27
	Step 2: Describe Application	30
	Step 3: Define Application I/O Wiring Specifications	33
	Step 4: Configure Hardware and Software Resources	36
	Step 5: Write the Program.	42
	Step 6: Test the Program	52
	Step 7: Transfer and Run the Program	60
	Step 8: Debug the Program	64
	Step 9: Manage the Program Report	70
Chapter 6	Monitoring an Application	73
-	Monitoring an Application	73
Index	7	75

Safety Information



Important Information

NOTICE

Read these instructions carefully, and look at the equipment to become familiar with the device before trying to install, operate, or maintain it. The following special messages may appear throughout this documentation or on the equipment to warn of potential hazards or to call attention to information that clarifies or simplifies a procedure.



The addition of this symbol to a Danger or Warning safety label indicates that an electrical hazard exists, which will result in personal injury if the instructions are not followed.



This is the safety alert symbol. It is used to alert you to potential personal injury hazards. Obey all safety messages that follow this symbol to avoid possible injury or death.

DANGER

DANGER indicates an imminently hazardous situation which, if not avoided, will result in death or serious injury.

WARNING indicates a potentially hazardous situation which, if not avoided, **can** result in death or serious injury.

CAUTION indicates a potentially hazardous situation which, if not avoided, **can** result in minor or moderate injury.

CAUTION

CAUTION, used without the safety alert symbol, indicates a potentially hazardous situation which, if not avoided, **can result in** equipment damage.

PLEASE NOTE

Electrical equipment should be installed, operated, serviced, and maintained only by qualified personnel. No responsibility is assumed by Schneider Electric for any consequences arising out of the use of this material.

A qualified person is one who has skills and knowledge related to the construction and operation of electrical equipment and its installation, and has received safety training to recognize and avoid the hazards involved.

About the Book



At a Glance

Document Scope	
	This document provides basic information and instructions for getting the TwidoSuite programming software set up and operating.
Validity Note	This documentation is valid for TwidoSuite Version 2.3.
User Comments	
	We welcome your comments about this document. You can reach us by e-mail at techcomm@schneider-electric.com.

Installation and Program Start

1

Overview

The TwidoSuite programming software is designed to run on various Windows 2000/XP/Vista operating systems. This chapter describes your computer system requirements to install and run this software. It also provides instructions for installing/uninstalling and starting the software.

What's in this Chapter?

This chapter contains the following topics:

Торіс	Page
System Requirements	10
Installing and Uninstalling the Software	11
Registering TwidoSuite	

System Requirements

Hardware Requirements

Your PC needs to meet the following minimum hardware requirements to run the TwidoSuite programming software:

Requirement	Minimum
computer	processor Pentium 466 MHz
RAM	128 MB
free hard drive space	100 MB

A CD-ROM drive is the required installation medium.

Software Requirements

The TwidoSuite programming software requires one of the following software operating systems:

Operating System	Edition/Service Pack	Special Considerations
Windows 2000	service pack 2 or above	For Windows 2000, Windows XP or
Windows XP	service pack 2 or above	Windows Vista, you need
Windows Vista	service pack 1 or above	TwidoSuite configuration software.

NOTE: Avoid patch 834707-SP1 (corrected by patch 890175) and patch 896358 which cause display problems with the Online Help.

The browser needs to be Microsoft Internet Explorer 4.01 or higher.

Connection to a Twido PLC

The TwidoSuite programming software runs on a PC that connects to the RS-485 programming port on the Twido PLC. You need to make the connection with a special TSXPCX1031 programming serial cable, which ships with the software.

INOPERABLE EQUIPMENT

Do not connect the communications cable to the controller before connecting it to the PC. Always connect the cable to the PC first.

Failure to follow these instructions can result in injury or equipment damage.

For more information about the required hardware connections, refer to the *Twido* controllers hardware guide for compact and modular bases.

Installing and Uninstalling the Software

Before You Start

Before you install the TwidoSuite programming software:

- uninstall any previous version of the TwidoSuite programming software (note that if you own a version of the TwidoSuite programming software, uninstall it as well for TwidoSuite is compatible with automation projects created with any version of TwidoSuite),
- close all Windows applications and virus-protection software.

Installing the Software

To install the TwidoSuite programming software:

Step	Action	Result
1	Insert the TwidoSuite CD in your PC's CD-ROM drive.	If the AUTORUN function is activated, the installation will start automatically, then go to step 4. Otherwise go to step 2.
2	If the installation does not start automatically, click Start \rightarrow Run.	The Run dialog box will appear.
3	Enter [Drive:]\setup.exe, then click OK.	The language selection screen appears.
4	Choose a language and click OK .	A message appears asking you if you want to register your copy of the software.
5	To register the software, click Yes . To run the software without registering it, click No .	An unregistered software package will run for 30 days, then stop running. You will need to uninstall the expired software before installing a new version. The new installation must be registered before it will work.
6	Choose the installation language among the list of available languages.	The software will be installed in both the selected local language and in the English version. You will later be able to execute the software in either of these languages by selecting the execution language from the TwidoSuite Application Launcher.
7	Follow the remaining on-screen installation instructions.	Once the software has been installed, an icon appears on your desktop, which you can double-click to start the software: TwidoSuite

Uninstalling the Software

To uninstall the TwidoSuite programming software from your computer, choose the following path: Start \rightarrow Control Panel \rightarrow Add/Remove Programs

Registering TwidoSuite

Introduction

Take a few minutes to register this software and become a member of the Schneider automation community.

Registering is free and it will keep you updated with the latest product news, software and firmware upgrades for your Twido controller.

NOTE: There is a 30-day trial period for this software. After expiry of the trial period, you **must** register to be able to continue using this software.

How to Register TwidoSuite

1. Go to Miscellaneous 🔽



- 2. Click About on the task bar.
- Complete the License form with "Company", "User" and "Serial Number" information, and press Now.

Result: This starts the TwidoSuite Registration Wizard.

- Follow the onscreen instructions to register your copy of the TwidoSuite software. Note: There are four possible ways to register: Web, Phone, Fax, and E-mail.
- 5. Read the Terms of Service, acceptance is required.
- 6. Submit the registration.

Launching TwidoSuite

2

Program Start

How to Start the Program

You can either start the program via the TwidoSuite Application Launcher:

- from the Start → Programs → Schneider Electric → TwidoSuite → Application Launcher path
- or from the desktop Application Launcher shortcut that has been installed with the program:



TwidoSuite

Application Launcher Options

The Application Launcher constitutes the launch center for the TwidoSuite software suite.

The TwidoSuite application comes in several language pairs available from the Schneider Electric download site:

- English-French
- English-German
- English-Spanish
- English-Italian
- English-Chinese(simplified)

Depending on which language pair you installed, it lets you run TwidoSuite in English (default language) or the other installation language.

Use the Application Launcher to start TwidoSuite in:

- Programming Mode
- Monitoring Mode
- PLC Firmware Update

Additional Features

Use the additional features to:

- see What's new? New ,
- view the Video Demo

NOTE: By default the Video Demo is shown at TwidoSuite startup. To disable this feature uncheck the box "Show video at startup" at the bottom of the video screen.

TwidoSuite Application Launcher

The following figure shows an example of the TwidoSuite Application Launcher for the English-French installed language pair:



Upgrading the Twido Firmware

Twido PLC Firmware Update

Overview

NOTE: The Schneider Electric Twido PLC is delivered with firmware installed. The procedures described for loading new firmware are only required if an update is being made. Before replacing the firmware, you should carefully study the corresponding instructions and contact the Schneider Electric support center.

When the TwidoSuite software is connected to the PLC, the firmware version that you are currently using for your Twido PLC can be found via the **Miscellaneous** button:



The **Twido Windows Executive Loader Wizard** is a Windows-based program that guides you through the steps needed to update the **Firmware Executive** in your Schneider Electric Twido programmable controller. The Firmware Executive is the operating system that runs your applications and manages controller operation.

The wizard provides an intuitive, point-and-click user interface that guides you through the steps of the update procedure. It provides directions to quickly download the latest version of the executive for your controller.

See the *Executive Loader Wizard User Guide* for detailed instructions. This guide can be accessed using the Exec Loader utility online help.

Opening the Exec Loader Wizard

LOSS OF APPLICATION

Do not update the Controller executive without first verifying that a copy of the current control application has been saved on the PC.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

You can open the Executive Loader Wizard from the TwidoSuite Application Launcher by selecting the **PLC Firmware Update** option.

New Firmware (Basic Steps)

There are four steps required to upgrade your executive. The wizard provides a window for each step and online help is available for each step. The following table summarizes each step:

Step	Window	Function
1	Welcome	Introduces the Executive Loader Wizard.
2	Parameters	Selects the correct executive file to transfer to your controller, and selects the PC serial port to communicate with the controller.
3	File and Device Properties	Compares the hardware IDs and the executive version information for the executive file and the controller.
4	Transfer Progress	Monitors the transfer of the executive file to the controller.

NOTE: Loading the firmware may not be interrupted under any circumstances as it means the module can no longer be accessed, including via the Executive Loader Wizard. Ensure that neither the communication connection nor the main power input is disconnected or deactivated in any way and do not deactivate the procedure with **Abort.**

The TwidoSuite Interface

4

Overview

This section describes the TwidoSuite:

- main window workspace
- preferences settings

This section also provides a work flow for creating a TwidoSuite project (see *Application Steps/Substeps Bar, page 19*).

What's in this Chapter?

This chapter contains the following topics:

Торіс	Page
Main Window	18
Setting Preferences	22

Main Window

TwidoSuite Workspace

Application steps bar	Program substeps bar	Taskbar
Project Describe Progra	m Report Configure Program	My project
		Configure the Herdware Configure the data Configure the behavior Define the protections
Description of the module Refer Description of the module Desc Module configuration.	ence num TWDLMDA200T Address 2 1 iption Modular base controller, 12 24V DC inputs, 8 ouputs (0.3A source transistors). Removable ML connectors. pply Cancel	
Used Address Symbol Used By F 12 %0.0 □ %0.0 □ %0.1 □ %0.2 □ %0.4	iltering Latch? Run/Stop? Deactivation High Priority S 3 ms F = - 3 ms F = - 3 ms F = Not used F 3 ms F = Not used F 3 ms F = Not used F	<u>SR Number -</u>
Table of outputs Used Address Symbol Status? U: V %00.0 V %00.1 V %00.2 W %00.3	ed By	Ť.
 Error list box	Quick access bar Functions	s bar



Application steps bar:	Displays TwidoSuite's 4 Application Steps (icons and titles), Project, Describe, Program, and Report buttons.
Program substeps bar:	Displays the 3 Program substeps (Configure, Program, Debug). It is showing only when the Program step is selected.
Taskbar:	Provides access to all the tasks that you can perform under the selected application step or substep.

Functions bar:	Provides access to special functions associated to the selected task.
Quick access bar:	Displays at all times Previous/Next commands, Save and Analyze Program shortcuts.
Editors and Viewers:	Editors and viewers are TwidoSuite windows that organize programming and configuration controls for efficient development of applications.
Error list box bar:	Displays information about the application, the controller, and TwidoSuite.

Display Options

	Maximizes the main window
	Minimizes the main window
×	Closes the TwidoSuite application
7	Docking button for the Application Steps bar
	Resizes the main window

Application Steps/Substeps Bar



Project

This is the first step in creating/opening an application. The Application Steps/Substeps Bar displays the name of the open application in the top-right corner.



Describe

This is the second step in building the Twido automation application. The Describe step lets you select hardware resources from the catalog and describe how equipment interconnect with one another via networks.



Quick Access Bar

Ð	Return to previous task, as you left it
\Rightarrow	Move back to next task, as you left it
	Save current project
P	Analyze Program
S	Launches and stops the Simulator .

Setting Preferences

Displaying Preferences

Click the **Preference** icon on the Steps bar to display the Preferences window as shown below.

Preferences Window

Preferences										Apply	Restore
Default project dir	ectory		Directo	oty:		C:\Progra	m File\Schne	eider Elec	tric\Twido	Suite\My pro	oject
Default projects			C Non C Schi C Cust	e neider default tomized		C:\Progra	m File\Schne	eider Elec	tric\Twido	Suite\My pro	oject
Default program e	ditor		€ Lado	ler							
Autosave project			€ Yes € No		every	11	5 🝸 minute	IS			
Default backgroun	d color) Clear		н н	· ·	, Dark				
Default project im	age		C Defa	ult image onalized imag	je	C:\Docum	ents and Se	ttings∖Adr	ministrate	ur\My docum	ients\
Default functional	levels of applica	s of applications									
					The	very lowe:	st				
			C Man	ual	Manua Level Level Level Level	1 manager 1.0 2.0 2.5 3.0	ment —				
Connection mana	gement										
	Name	Connection	n type	IP / Phone	Punit /	Address	Baud rate	Parity	Stop bit	s Timeout	Break timeout
	COM1	Serial		COM1	Punit					5000	20
	COM2	Serial		COM1	Punit					5000	20
	My connection 1	Serial		192.168.1.1	Direct					5000	20
	Modern connection	Ethernet		XXXXXXXXXX			19200	None	1	Modbus driv	20 er parameters Delete

Customize Project Preferences

- Set the default project directory path
- Set the default/customize projects

- Set the default program editor (Ladder or List)
- Set the **autosave** options
- Set the background color
- Set the default/custom project image
- Select the **automatic/manual functional level** management method to implement at project start
- Add/update/remove connections by using the connections management table

Creating and Editing a Program

Overview

In this section, you will learn how to create and edit a program with TwidoSuite.



To start TwidoSuite you need open the Application Launcher. Click the ^{TwidoSuite} icon located on your PC desktop.

The Application Launcher dialog box appears as shown below:



From TwidoSuite Application Launcher, you have access to the following modes:

- TwidoSuite Programming Mode
- TwidoSuite Monitoring Mode
- PLC Firmware Update utility

What's in this Chapter?

This chapter contains the following topics:

Торіс			
Step 1: Create a New Project			
Step 2: Describe Application			
Step 3: Define Application I/O Wiring Specifications	33		
Step 4: Configure Hardware and Software Resources	36		
Step 5: Write the Program	42		
Step 6: Test the Program	52		
Step 7: Transfer and Run the Program	60		
Step 8: Debug the Program	64		
Step 9: Manage the Program Report	70		

Step 1: Create a New Project

WARNING

LOSS OF CONTROL

- The designer of any control scheme must consider the potential failure modes of control paths and, for certain critical control functions, provide a means to achieve a safe state during and after a path failure. Examples of critical control functions are emergency stop and overtravel stop, power outage and restart.
- Separate or redundant control paths must be provided for critical control functions.
- System control paths may include communication links. Consideration must be given to the implications of unanticipated transmission delays or failures of the link.
- Observe all accident prevention regulations and local safety guidelines.¹
- Each implementation of this equipment must be individually and thoroughly tested for proper operation before being placed into service.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

¹ For additional information, refer to NEMA ICS 1.1 (latest edition), "Safety Guidelines for the Application, Installation, and Maintenance of Solid State Control" and to NEMA ICS 7.1 (latest edition), "Safety Standards for Construction and Guide for Selection, Installation and Operation of Adjustable-Speed Drive Systems" or their equivalent governing your particular location.

How to Start the Project Manager

Click the **Project** icon on the TwidoSuite workspace Steps bar to display the Project window and create/open/edit a TwidoSuite project.

Project Window

	Project information	<u>,</u>		
Project management	File information -			
Update the project information	Project	My project		
Open an existing project	Directory			
Open a recent project	Directory	G:\Program File\Schneider Electric\TwidoSuite\		
Save current project	Project information			
	Author	Author's name		
	Department	Service		
Create a new project	Index	version		
In this screen you can: -select the project name and enter the	Industrial Property			
-attach a photo to the project in the "image" tab. -Click on "Create" to create the project.	Comment Des	cription Image		
Create				
and the second se				

How to Create a New Project

- 1. Click Create a new project in the "Project Management Actions Pane".
- 2. Enter a descriptive name for the project in the File Information frame. A valid project name can contain up to 36 alphanumeric characters (spaces allowed).
- **3.** Specify the new path for the **project directory** or use the default path. In the **Directory** text box, either enter directly the storage directory path or click the Browse button located immediately to the right of the Directory text box to locate the folder where the project files will be stored.
- 4. Enter project authoring information in the **Project Information** frame. This includes providing **Author**'s name, **Department** name, project version number in **Index** field and **Industrial Property.**
- 5. In the **Comments** tab, include the name of the project and write a brief description. Use the right scrollbar to read the complete text.

- 6. Select the **Image** tab and click **Modify** to customize the project picture, or use the default picture. The project picture is printed on the front cover of the project report. For more details, refer Manage the Program Report (*see page 70*). A valid picture file must be in the .BMP format.
- 7. Click Create to save your changes to the new project file.

Step 2: Describe Application

A WARNING

LOSS OF CONTROL

- The designer of any control scheme must consider the potential failure modes of control paths and, for certain critical control functions, provide a means to achieve a safe state during and after a path failure. Examples of critical control functions are emergency stop and overtravel stop, power outage and restart.
- Separate or redundant control paths must be provided for critical control functions.
- System control paths may include communication links. Consideration must be given to the implications of unanticipated transmission delays or failures of the link.
- Observe all accident prevention regulations and local safety guidelines.¹
- Each implementation of this equipment must be individually and thoroughly tested for proper operation before being placed into service.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

¹ For additional information, refer to NEMA ICS 1.1 (latest edition), "Safety Guidelines for the Application, Installation, and Maintenance of Solid State Control" and to NEMA ICS 7.1 (latest edition), "Safety Standards for Construction and Guide for Selection, Installation and Operation of Adjustable-Speed Drive Systems" or their equivalent governing your particular location.

How to Start the Describe Feature

Click the **Describe** icon the Describe window.



on the TwidoSuite workspace Steps bar to display

Describe Window

In the Describe window, you declare the Twido automation system elements selecting hardware resources from the catalog and describing how equipment interconnect with one-another via networks.



Elements of the Describe window:

- **Graphic Pane:** This is where you build the graphical representation of your application by adding hardware elements. Drag selected hardware elements from the catalog pane to the graphic pane to gradually construct your automation system. You use the graphic pane to declare networks and how equipment interconnects with one another, as well.
- **Describe tool bar:** Use the Describe tool bar to manage the graphic pane and elements.



The bottom part of the pane provides a short description of the selected hardware element.

• **Bill of materials pane:** This dockable pane shows a bill of materials of the hardware elements that currently make up the open project. You can conveniently click **Export** to save the bill of materials to a file in a Comma Separated Value (.CSV) format.

How to Describe Your Application

- 1. Use drag-and-drop to place catalog elements in the graphic pane, starting with the base controller (compact or modular), then adding expansion modules and options as supported by the controller and as required by your application.
- **2.** Configure communication ports by double-clicking the ports graphical representation in the graphic pane.
- **3.** Use drag-and-drop to place network elements available from the catalog pane in the graphic pane.
- 4. Click to select a Twido communication port and drag the cursor to draw the network links between the Twido base controller and network elements. Connect network elements with one another in the same manner to build network links.

NOTE: To find out more about describing applications, declaring network elements and configuring networks, please refer to the *TwidoSuite Operation Guide - Online Help.*

Step 3: Define Application I/O Wiring Specifications

Introduction

Before you proceed with programming of your application, you must set your application I/O wiring specifications.

A DANGER

HAZARD OF ELECTRIC SHOCK, EXPLOSION OR ARC FLASH

- Disconnect all power from all equipment including connected devices prior to removing any covers or doors, or installing or removing any accessories, hardware, cables, or wires except under the specific conditions specified in the appropriate hardware guide for this equipment.
- Always use a properly rated voltage sensing device to confirm the power is off where and when indicated.
- Replace and secure all covers, accessories, hardware, cables, and wires and confirm that a proper ground connection exists before applying power to the unit.
- Use only the specified voltage when operating this equipment and any associated products.

Failure to follow these instructions will result in death or serious injury.

MALFUNCTIONS OF OUTPUTS

Use appropriate interlocks where personal and/or equipment hazards exist. Outputs can malfunction and remain ON or OFF.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

I/O Wiring Specifications

It is good practice to draw up a small sketch of your application I/O wiring.

INCORRECT EQUIPMENT OPERATION

Be sure that the wiring is in agreement with the TwidoSuite configuration. If you have wired your input for a voltage measurement, and you configure TwidoSuite for a current type of configuration, you may permanently damage the analog module.

Failure to follow these instructions can result in injury or equipment damage.

The following are I/O specifications for the automatic-watering system:

Input specifications

- %I0.0 input from water high level sensor in water tank
- %I0.1 input from water Iow level sensor in water tank

Output specifications

- %Q0.0 output to water pump actuator
- %Q0.1 output to irrigation control valve

RTC Specifications

• RTC option must be installed on Twido 10 I/O base controller.



I/O wiring specifications are outlined in the following simplified wiring sketch:

Step 4: Configure Hardware and Software Resources

Introduction

Now that you have declared the hardware elements in the Describe step, you will need to configure hardware and software resources.

To have access to hardware and software configuration options, select



Configure Hardware Resources

LOSS OF CONTROL

- The designer of any control scheme must consider the potential failure modes of control paths and, for certain critical control functions, provide a means to achieve a safe state during and after a path failure. Examples of critical control functions are emergency stop and overtravel stop, power outage and restart.
- Separate or redundant control paths must be provided for critical control functions.
- System control paths may include communication links. Consideration must be given to the implications of unanticipated transmission delays or failures of the link.
- Observe all accident prevention regulations and local safety guidelines.¹
- Each implementation of this equipment must be individually and thoroughly tested for proper operation before being placed into service.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

¹ For additional information, refer to NEMA ICS 1.1 (latest edition), "Safety Guidelines for the Application, Installation, and Maintenance of Solid State Control" and to NEMA ICS 7.1 (latest edition), "Safety Standards for Construction and Guide for Selection, Installation and Operation of Adjustable-Speed Drive Systems" or their equivalent governing your particular location.
Projec	t Describe	Pro gram Rep	2 Soort			Telemccanique My project	8
				Configure	Program	Debug	
Description of the	e module	Reference num Description	TWDLMDA20DT	Add	ress D ts, 8 ouputs (D.3A		Configure e Hardwar Configure the data Configure he behavio Define e protection
Module configu	ration.	Apply	Cancel			- 11	
Table of inputs —							
Used Address %10.0 %10.1 %10.2	Symbol Used	3 By Filtering 3 ms 3 ms 3 ms 3 ms 3 ms 3 ms	Latch? Run/Stop?	Deactivation Not used Not used Not used	High Priority SR	Number 1	
□ %I0.3 □ %I0.4							
						II	
%0.3 %0.4 %0.4 Xeed Address √ %00.0 %00.0 %00.0 %00.0 %00.2 %00.3	Symbol Stat	tus? Used By					

Select the $Program \rightarrow Configure \rightarrow Configure Hardware$ task to open the hardware configuration window.

-

...

....

Graphic Pane: Picture of the controller and its expansions

Configuration Pane: Description (with configuration) of the currently selected hardware elements

Configurable hardware resources include:

- · Base and remote controllers discrete inputs and outputs
- Expansion I/O modules parameters, such as analog modules
- AS-Interface module and slave devices parameters
- CANopen master module and slave devices parameters
- Options parameters

Automatic-Watering System Example

In this application example, you will find it useful to symbolize inputs and outputs *(see page 33)*.

To configure symbols for I/Os, follow these steps:

- Select the Program → Configure → Configure Hardware task to open the hardware configuration window.
- 2. Click once on the controller picture to select the TWDLCAA10DRF controller in the graphic pane.
- **3.** In the configuration pane, enter symbolic names for the I/Os you want to symbolize, for example:
 - WATER_HIGH_LEVEL, in %I0.0 symbol field
 - WATER_LOW_LEVEL, in %I0.1 symbol field
 - WATER_PUMP, in %Q0.0 symbol field
 - IRRIGATION_VALVE, in %Q0.1 symbol field

Note: Symbols are fixed in upper-case format. A valid symbol can contain any combination of 32 characters: (A-Z),(0-9), and (_). No spaces allowed.

4. Changes are effective as soon as the cursor leaves the current input or output line.

Configure Software Resources

WARNING

LOSS OF CONTROL

- The designer of any control scheme must consider the potential failure modes
 of control paths and, for certain critical control functions, provide a means to
 achieve a safe state during and after a path failure. Examples of critical control
 functions are emergency stop and overtravel stop, power outage and restart.
- Separate or redundant control paths must be provided for critical control functions.
- System control paths may include communication links. Consideration must be given to the implications of unanticipated transmission delays or failures of the link.
- Observe all accident prevention regulations and local safety guidelines.¹
- Each implementation of this equipment must be individually and thoroughly tested for proper operation before being placed into service.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

¹ For additional information, refer to NEMA ICS 1.1 (latest edition), "Safety Guidelines for the Application, Installation, and Maintenance of Solid State Control" and to NEMA ICS 7.1 (latest edition), "Safety Standards for Construction and Guide for Selection, Installation and Operation of Adjustable-Speed Drive Systems" or their equivalent governing your particular location.

Select the $\textbf{Program} \rightarrow \textbf{Configure} \rightarrow \textbf{Configure}$ bata task to open the software configuration window.

	Jeschbe 110	gram ree	pon					
Object Categories Simple objects Function blocks I/O objects	Define Allocatio Table	Objects	is 💌 M	Co Number of o	onfigure ojects 0	Program Affected (Debug 0 Maxi: 3000	Configur the Hardw Configur the data
Advanced objects	All		0/14/07	C maked				Define
		Equ. Usea	%MV/	Symbol .				the protect
o:			% M/W 1	[
Simple objects			%MM/ 2					
% M		-	%MM/ 3					
%MW			%MW.4					
2011		E	%MW.5					
%MD		Π	%MW.6					
% MF			%MW.7					
%KW			%MW.8					
% KD			%MW.9					
76KD		Γ	%MW.10					
%KF			%MW.11					
			%MW.12					
	-		%MW.13					
			%IVIVV.14					
		-	%MW/16					
	-		%M0A/ 17					
		E	%MW.18					
	-	-	9/ 1/0 1/10					

Configurable software resources include:

- Simple objects
 - Memory bits (%M)
 - Memory words (%MW, %MD, %MF)
 - Constants (%KW, %KD, %KF)
- Function blocks
 - Timers
 - Counters
 - Drum controllers
 - LIFO/FIFO registers
 - Shift bit registers
 - Step counters
- I/O objects
 - Fast counters
 - PLS/PWM pulse generators
 - Very fast counters

- Advanced objects
 - Schedule blocks
 - PID
 - Macro functions

NOTE: Internal memory objects such as system bits and words, memory bits and words, and network exchange words are **non-configurable** objects.

Automatic-Watering System Example

In this application example, you will need to configure two software objects:

- One Schedule Block (Real Time Clock 0) that will manage the weekly watering schedule.
- One Counter (%C0) that will serve as a maintenance cycle counter.

Configuring schedule blocks

- To support schedule blocks, make sure the RTC option is installed on your TWDLCAA10DRF controller.
- Schedule blocks are non-programmable objects that do not need any declaration in the Ladder or List program. You simply need to enable them and configure their respective parameters.

To configure the Schedule Block (Real Time Clock 0), follow these steps:

- Select the Program → Configure → Configure Data task to open the software objects configuration window.
- From the "Object Categories" frame, select Advanced objects.
 Result: The list of available advanced function blocks for that particular controller is displayed in the dedicated "Advanced objects" frame below.
- From the "Advanced objects" frame, select %SCH Schedule blocks.
 Result: The schedule blocks configuration window appears in the center pane. Available schedule blocks (numbered 0 to 15) are listed in a table.
- Select the schedule block you want to configure in the table: Real Time Clock 0. Result: By default, the schedule block is disabled and all fields appear as nonconfigurable in the configuration window.
- 5. Click the **Configured** checkbox to activate the configuration fields and follow these steps to configure the schedule block (the following settings are given as an example only):
 - a. Enter the Output Bit address. In this application, this is the address of the output terminal connected to the control valve of the irrigation system: %Q0.1
 - **b.** Select **Start Month** and **End Month** for starting and ending the Schedule Block.

Range: January to December.

c. Select **Start Date** and **End Date** for the day of the month for starting and ending the Schedule Block.

Range: 1 to 31 (depending on month selection).

- d. Select the Start Time and End Time for setting the time of day for starting and ending the Schedule Block.
 Range: 00:00 to 23:59.
- e. Select the **Days of the Week** to activate the schedule block output. Checked boxes indicate the days that the output device is activated.
- 6. Use the Up/Down keys to scroll through the list of schedule blocks in the table or use the mouse pointer to select a particular schedule block.
- 7. Changes are effective as soon as the cursor leaves the current schedule block line.

Now that you have configured the schedule block, follow these steps to configure the **maintenance cycle counter (%C0):**

- Select the Program → Configure → Configure Data task to open the software objects configuration window.
- From the "Object Categories" frame, select Function blocks.
 Result: The list of available function blocks for that particular controller is displayed in the dedicated "Function blocks" frame below.
- From the "Function blocks" frame, select Counters.
 Result: The counters configuration table appears in the center pane. Available counters range from #0 to #127.
- 4. Select the up/down counter you want to configure in the table: %C0.
- **5.** For the selected up/down counter set the corresponding fields in the table, as follows (the following settings are given as an example only):
 - a. Click the Symbol text box and enter a symbolic name for this counter: MAINTENANCE_REQUIRED (for example.)
 Note: Symbols are fixed in upper-case format only. A valid symbol can contain any combination of 32 characters: (A-Z),(0-9), and (_). No spaces allowed.
 - b. Select a Preset value: 100 (watering cycles, for example.)
 Range: 0 to 9999.
 Default: 9999.
 - **c.** Select **Adjustable** option to allow the Preset value to be changed from within Animation Tables.
- 6. Use the Up/Down keys to scroll through the list of counters in the table or use the mouse pointer to select a particular counter.
- 7. Changes are effective as soon as the cursor leaves the current counter line.

NOTE: Counters are programmable objects that need to be controlled in the Ladder or List program. It is at that stage that you will specify whether the counter used is a up or down counter.

Step 5: Write the Program

Introduction

Use the **Program Editor** to develop the main program which is the core of your Twido automation application. Major programming and configuration features include reversible ladder and list language programming.

This section will focus on providing you the basics of Ladder language programming in TwidoSuite program editor. For details on List language programming and Ladder/List reversibility features, please refer to the *TwidoSuite Programming Guide* on the CD-ROM.

To have access to the program editor, select **Program** \rightarrow **Program** \dashv **Program** \dashv **Program** \dashv **Program** \dashv **Program** on the TwidoSuite Steps bar and click **Edit Program** on the task bar.

NOTE: In program mode, the task bar provides access to the **Symbol Editor** as well.

Program Edition Window

The **Program Edition** window features the **Program Editor** and **five browsers and tools** available on the functions bar, as described in the following figure:



Show/hide Data Browser

Ladder Editor Elements

The **Ladder Editor** is a graphics-based, program editor used to view, create and edit ladder programs.

When you select **Ladder** in the program tool bar drop-down list box, the program editor switches to Ladder mode. The following figure describes the various elements that make up the ladder editor:



Program Edition Tool Bars

3 ladder programming tool bars (see figure above) are available that allow you to easily edit programs and graphically enter ladder instructions:

- Program Tool Bar
- Ladder Palette Tool Bar
- Extended Ladder Palette

Program Tool Bar

La	
Li	st <
1	Toggle Ladder/List mode
2	Add section
3	Insert section
4	Add subroutine
5	Cut in 2 sections
6	Zoom ratio (default is 100%)
7	Cut
8	Copy
9	Paste
10	Undo
11	Redo
12	Display in beyadecimal or decimal
13	Display/Hide rung comments
14	Display/Hide ladder elements comments
15	Display/Hide symbols

Ladder Palette Tool Bar



Toggle Extended Ladder Palette sections

- 1 Add rung
- 2 Insert rung
- **3** Add normally open contact
- 4 Add normally closed contact
- 5 Add coil
- 6 Add inverse coil
- 7 Add link
- 8 Remove link
- 9 Add Comparison block
- 10 Add Operation block
- 11 Add Timer block
- **12** Add Counter block
- 13 Add Jump or Subroutine Call
- 14 Extended Ladder Palette buttons (see below)

Extended Ladder Palette



- 1 Contacts: Normally Open, Normally Closed, Rising Edge, Falling Edge
- 2 Special Contacts: XOR, XORN, XORR, XORF, OPN, SHORT
- 3 Coils: Normal Coil, Inverse Coil, Set Coil, Reset Coil
- 4 Special Coils: JMP/SR, RET, END, Grafcet Coil 1, Grafcet Coil 2
- 5 Basic Function Blocks: %FC, %VFC, %PLS, %PWM
- 6 Advanced Function Blocks: %MSG, %R, %SBR, %DR, %SC

Overview of Ladder Programming

You write a ladder program in the logical order required to control a machine or process.

Sections/Subroutines

A TwidoSuite ladder program is made up of a sequence of sections and subroutines containing ladder rungs. Sections and subroutines are delimited by section/subroutine headers. They are numbered automatically by the TwidoSuite software.

The following figure describes a typical section header (subroutine headers are similar to this).



One line of up to 122 characters

Four lines of up to 122 characters each

Rungs

A ladder **rung** is similar to a relay logic diagram. Each rung consists of one network of linked graphical elements organized in a programming grid starting with a potential bar on the left and ending with a potential bar on the right.

The following figure describes a typical ladder rung.



none if the rung has not been modified

NOTE: Programs are limited to a total of 128 sections and subroutines with a maximum of 64 subroutines (SR0 to SR63).

How to Edit a Program

The following procedure gives you the basics to start editing a ladder program.

1. When you start writing a new program, press the **Add Section** icon so on the program tool bar at the following prompt.



Result: The first section is inserted in the ladder editor, displaying the first empty rung, as shown below. (Note that a program **must** contain at least one section.)



- 2. Double-click the section header to enter the following:
 - Section title
 - Comments
- 3. Double-click the rung header to enter the following:
 - Rung title
 - Comments
 - Declare rung type: Standard or Label (%Li)
- **4.** Select the empty horizontal link that runs between the rung left and right power lines.

Result: The selected link is highlighted in blue..



5. Click the Normal contact icon (example) on the Ladder Palette to insert the input graphical instruction.

Result: The normal contact is inserted in the leftmost part of the rung.



- 6. Repeat steps 4 to 5 to insert other graphical instructions, as needed.
- 7. A valid rung must always feature an output element (coil or operation block). Click

the **Coil** icon (example) on the Ladder Palette to insert the output graphical instruction.

Result: The coil element is inserted in the rightmost part of the rung.



Note: At this stage, you will note that the red color bar shows that the rung is still invalid.

 You must specify an address to each element in the rung. Click the address field above each element and enter the desired address. Enter %10.0 for the input contact and %Q0.0 for output coil (example). Note that you may also optionally specify a symbol and comment for each element.



Result: The yellow color bar indicates that this rung is valid, but has not been analyzed (compiled with the program) yet.

9. Click the Analyze icon III to start the program validation process and check for possible user program errors in the Error list box.

NOTE: To find out more about program edition rules and procedures, please refer to the *TwidoSuite Operation Guide - Online Help.*

Example Program for the Automatic-Watering System

This section gives you the ladder program that applies to the automatic-watering system example. This application consists of 2 independent processes:

- Water tank level management
- Watering Count

This wil require to create 2 sections in the program, one for each process.

Water tank level management section

Insert the first section of the program, and create the following program.

1 LD WATERING TANK LEVEL MANAGEMENT	This section describes how regulate the watering tank level
Rung 0	% <u>00.9</u>

Description of the water tank level regulation process:

- 1 Whenever the water low-level is reached (%I0.1 is closed), the water-pump is started (%Q0.0 is closed). Note that %I0.0 remains normally closed.
- 2 Whenever the water high-level is reached (%I0.0 is open), the water-pump is stopped (%Q0.0 coil is activated and %Q0.0 contact is closed). Note that the %Q0.0 contact allows to keep the water-pump running until the water high-level is reached.

Watering count

Add a section to the program, create the following program that will count the watering cycles and save your project. (**Note:** If you have not done it yet at the Data Objects Configuration stage, double-click the %C0 element and set the **Preset** value to **100** cycles in the Counters table.)



Description of the watering-count process:

- 1 Whenever the watering control valve is activated (%Q0.1 is closed), the counter %C0 is incremented.
- 2 When the counter current value reaches 100, the memory bit %M0 is set to 1. Memory bit %M0 can be used to control an LED that will indicate that maintenance is required after completion of the 100 watering cycles. Note that you may connect a push button to the R input to manually reset the maintenance cycle counter.

Save the Program

Once you have finished writing your program, you can save your program in one of 2 ways:

• Provided that you have already given a name to your application and specified the project directory (see page 27), click the **Save current project** shortcut



• Select \bigcirc Project \rightarrow Save current project task and click the Save button.

Result: The project files containing the application program are saved to the disk in the project directory for which the location has been specified in the project file information window.

NOTE: It is good practice to frequently save your project to the PC disk as you are writing larger ladder/list instructions programs to prevent any significant loss of work due to power shut-down or other computer-related problems.

Step 6: Test the Program

Introduction

TwidoSuite offers a simulator function that enables you to test a newly written program without loading it on a controller. The Twido Simulator lets you run the program and test different parameters in order to see if the expected responses are occurring.

WARNING

UNINTENDED EQUIPMENT OPERATION

Only qualified personnel with knowledge of the control system logic and its effect on the machine or process should execute Controller Operations, Online Programming, Forcing and/or other changes to the controller's memory.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

Starting Twido Simulator

To start the Twido Simulator select **Program** \rightarrow **Program** and click the Twido

Simulator button (S) at the bottom right of the TwidoSuite screen.

Result:

- TwidoSuite switches automatically to **Program** → **Debug** → **Animate the program**.
- The Twido Simulator overview window appears.
- The Dashboard pops up.
- If an RTC is configured or embedded, the Time Management Panel is also displayed.

The Simulator loads the configuration you have created in the Describe screen.

NOTE: Network elements, Exchange Instruction (EXCH), PID, FC, VFC, and PLS/PWM cannot be simulated.

Using Twido Simulator

Once the Simulator is launched you can use the functions that are available in debug mode. These are:

- RUN the program
- Manage animation tables
- Monitor hardware configuration
- Monitor software configuration
- Monitor described configuration
- Monitor the results of program execution

You can find more information on animating tables and managing animation tables in Debug the Program *(see page 65)*.

Twido Simulator Overview Window

The Twido Simulator overview window shows the state of inputs/outputs for all the described base controller and any expansion modules.

The overview window is shown below:



1. Click to minimize to tray.

When the overview window is minimized, the Twido Simulator icon appears in the status area (on the bottom right of your screen). Double click on this icon to restore the overview window.

- 2. Inputs states:
 - Click to set/reset the corresponding input
 - Double click to open the discrete input settings window.
- 3. Outputs states: double click to open the output tracing window.
- 4. Click to always toggle the overview window on top
- 5. PWR LED: Indicates if the simulated PLC is powered up.
- 6. RUN LED: Indicates the state of the simulated PLC.
- 7. ERR LED: Indicates detected errors of the simulated PLC.
- 8. STAT LED: The operation of the STAT LED is defined by user logic
- 9. Base controller and expansion modules references
- 10. Expansion modules that cannot be simulated.

Right click on the Overview Window to expand the following contextual menu:

- Time Management: Opens the Time Management panel.
- Output Tracing: Opens the Output Tracing window.

To access analog input settings, double click on the analog input LED.

To access discrete input settings, double click on the discrete input LED.

Twido Simulator Dashboard

You can use the Twido Simulator dashboard to issue the following commands to the simulator:

- Run (in simulate mode)
- Stop
- Initialize (H)

When the TwidoSuite application is in simulate mode, these commands can be selected from the Twido Simulator dashboard shown below:



RUN, ERR, and **STAT** LEDs are simulated in the Twido Simulator dashboard as they would appear on a connected base controller (for details about these LEDs, see the Twido Hardware Reference Guide).

Using Twido Simulator Dashboard

To close the control panel dashboard:



To re-open the dashboard, click the button as shown below:



Expanding Twido Simulator Dashboard

To expand/reduce the control panel dashboard, click as shown below



The dashboard is then expanded as shown below. It may be reduced again by clicking the same expansion/reduction button.

	×
Application name :	My Twido
Twido state :	Stopped
Reference :	TWDLMDA40D-K
Firmware version :	4.10
Current time :	
NO failured :	TRUE
NO forced :	
Current PLc scanning period	: 0
Address used :	Punit
Port used :	
COMI	
LAc: NA	
LSt:	
TOUDLAD AND K	
	SIMULATION
O RUN	
• Error	
Stat	
🐼 Twic	oSuite
- Twice	loound

Time Management Panel

The Time Management Panel allows to control the timing of the simulation (Action on the time management panel modifies the RTC time accordingly and immediately), you can choose:

- The beginning and the end of the simulation
- To accelerate the simulation.

NOTE: The default initial time of the simulation is the time of your PC.

The default duration of the simulation is 7 days.

The Time Management Panel is shown below:



- **1.** Beginning time: Time at the beginning of the simulation
- 2. Simulation Period:
 - If this box is checked, then when end time is reached the simulator stops and a window pops up with the following text: End Time Reached! PLC switches to STOP even if you don't click OK.
 - If this box is not checked the simulation stays in RUN mode.
- 3. End time: Time at the end of the simulation
- 4. A cursor indicates the current time progression.

You can move manually the cursor to set current time.

- If the current time is former to the beginning time then the cursor will go on "Beginning"
- If the current time is posterior to the end time then the cursor will go on "End".
- 5. Simulator status:
 - Simulator in Stop mode
 - Simulator in Run mode
 - Simulator in fast forward
 - < : Simulator in fast rewind
- 6. Indicates the current time of the simulation
- 7. Back to beginning time
- 8. Fast rewind in time
- 9. Fast forward in time
- **10.**Go to the end time.
- 11.Set the level of fast forward/rewind in time

Setting Simulation Parameters

In order to run tests on your program, the Twido Simulator lets you set the input values and the configure which outputs are traced.

You can set both the discrete inputs and analog inputs.

- To open the discrete input settings window, double-click on the discrete input LED.
- To open the analog input settings window, double-click on the analog input LED.

You can also configure up to 8 outputs to be traced traced. You open the tracing configuration window by clicking the Configure button of the output tracing window.

Output Traces with the Simulator

The outputs tracing window shows the variation of analog and discrete outputs over time.

The outputs tracing window is shown below:



Stopping Twido Simulator

To stop the Twido Simulator, click the button S at the bottom right of the TwidoSuite screen.

After stopping the simulation TwidoSuite returns to the screen displayed before starting Twido Simulator.

NOTE: It is not possible to save the program while the Twido Simulator is active.

Step 7: Transfer and Run the Program

Introduction

In this section, you will find out how to transfer the program to the Twido PLC and start running your program on the controller.

LOSS OF CONTROL

- The designer of any control scheme must consider the potential failure modes of control paths and, for certain critical control functions, provide a means to achieve a safe state during and after a path failure. Examples of critical control functions are emergency stop and overtravel stop, power outage and restart.
- Separate or redundant control paths must be provided for critical control functions.
- System control paths may include communication links. Consideration must be given to the implications of unanticipated transmission delays or failures of the link.
- Observe all accident prevention regulations and local safety guidelines.¹
- Each implementation of this equipment must be individually and thoroughly tested for proper operation before being placed into service.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

¹ For additional information, refer to NEMA ICS 1.1 (latest edition), "Safety Guidelines for the Application, Installation, and Maintenance of Solid State Control" and to NEMA ICS 7.1 (latest edition), "Safety Standards for Construction and Guide for Selection, Installation and Operation of Adjustable-Speed Drive Systems" or their equivalent governing your particular location.

Transfer the Program

In order to run your application for debugging, you must first transfer it to the controller RAM.

Follow these steps to download your application program to the PLC:

- 1. If the PC is not yet connected to the controller, select a connection from the
 - connections table in $\textbf{Program} \rightarrow \textbf{Debug} \rightarrow \textbf{Connect}$ task and click Run.

This connection method allows to	Select a connection				
directly connect to the controller or to transfer an application from the PC to	Type Name		Connection method	₽/Phone	
he controller.	Project				
	Project	My connection 2	Serial	Punit	
	Project	My connection 3	Modem	555554443333,	
	Project	My connection 4	USB	USB,8	
	PC	USB	Serial	USB Punit	

Results: TwidoSuite tries to establish a connection with the controller and performs synchronization checks between the PC and the PLC applications.

• The Connection Test Table displays the results of 3 synchronization checks.

This connection method allows to di-	Select a co	nnection			
recity connect to the controller or to transfer an application from the PC to	Туре	Name	Connection method	P/Pho	ne
the controller.	Project	USB direct	USB	USB	
	Project	Ethernet direct	TCP/IP	192.168	3.0.1
	Project	Modem direct	MODEM	+3322	3 45 67 89
	Project	CON1 P2P	Série	COM1	ø
	PC	USB P2P	USB	USB_1	
				0.000	uniontion octoblic
	Connection The PC and Hardware co Controller ap	tests controller applications onfigurations match : : oplication not protecte	s do not match : immediate co transfer PG —> Controller is d : transfer Controller —> PC	possible is allowe	is not possible ! d
	Connection The PC and Hardware co Controller ap <u>Comparing</u>	n tests controller applications onfigurations match : oplication not protecte applications	s do not match : immediate cc transfer PC =>> Controller is d : transfer Controller =>> PC Project	onnection possible) is allowe	is not possible ! d Controller
	Connection The PC and Hardware co Controller ap Comparing Application n	n tests controller applications onfigurations match : opplication not protecte applications name	s do not match : immediate co transfer PG => Controller is d : transfer Controller => PC <u>Project</u> <u>VewEx</u>	onnection possible) is allower	is not possible ! d Controller ViewEx
	Connection The PC and Hardware or Controller ap Application n Base control Select a con	n tests controller applications onfigurations match : opplication not protecte applications name lier nnection method	s do not match : immediate ct transfer PC —> Controller is d : transfer Controller —> PC <u>Project</u> ViewEx TWDLGAA1	onnection possible) is allower 6DRF	is not possible 1 d Controller ViewEx TWDLGAA16DR
	Connection The PC and Hardware oc Controller ap Comparing Application n Base control Select a con	n tests controller applications onfigurations match :: opplication not protecte application name lifer nnection method	s do not malch : immediate co transfer PC Controller is d : transfer Controller	6DRF	is not possible ! d Controller ViewEx TWDLCAA16DR
	Connection The PC and Hardware cc Controller ap Comparing Application n Base control Select a con	n tests controller applications indigurations match :: opplication not protecte applications mane lier nection method immediate connect	s do not match : immediate co transfer PC> Controller is d : transfer Controller> PC <u>Project</u> VewEx TWOLCAAT	6DRF	is not possible ! d <u>Controller</u> ViewEx TWDLCAA16DR

Line 1: Comparison between the PC and the PLC applications

Line 2: Hardware compatibility check

Line 3: Security check (if the PLC application is valid), otherwise indicates if the PLC application is invalid.

• The **Application Comparison Table** is displayed only if both PC and PLC application are not identical.

2. If the PC and PLC applications are different, select **Transfer PC => Controller**.



- **3.** If the controller application is password protected, you are prompted for a password. Enter the password and select **OK** to continue the transfer.
- **4.** If the controller is running, an advisory box is displayed stating that to continue the transfer, the controller must be stopped.

If the controller is stopped, the transfer begins. If the controller is running, select **OK** to stop the controller and continue the transfer. Select **Cancel** to close the box and cancel the transfer.

An advisory dialog box is displayed indicating that the contents of the controller application will be overwritten.

 Select OK to continue the transfer.
 An option can be set to protect the application (see Security Features in the TwidoSuite Operation Guide - Online Help.)

NOTE: Symbols and program comments are not transferred to the controller.

Run the Program

Use the PLC **Soft Control Panel** to Run/Stop/Initialize a program that has been downloaded to the PLC (refer Transfer the Program *(see page 61)*).

To run the program that you have just transferred to the PLC, follow this procedure:

- If the connection between TwidoSuite and the PLC is not active, select a connection from the connections table in Program → Debug → Connect task and click OK to establish a connection.
- When a successful connection is established between TwidoSuite and the controller, the PLC Soft Control Panel dialog box appears in the form of a dashboard, always on top of your TwidoSuite workspace.



It features the following command buttons:



3. Click **RUN** to execute the TwidoSuite application program currently in controller's RAM.

Note: Each command requires confirmation before execution. **Result:** 3 soft panel LEDs (RUN, Error, Stat) provide live diagnostics (see *TwidoSoft Operation Guide -Online Help* for details).

UNINTENDED EQUIPMENT OPERATION

Be aware of the output default values when the controller is in STOP mode.

- The analog output is set to its fall-back position.
- The discrete output is set to zero.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

Using the Control Panel Dashboard

The Control Panel Dashboard is used in the same way as the Dashboard used for the Simulator, refer to Twido Simulator Dashboard (*see page 54*).

Step 8: Debug the Program

Overview

TwidoSuite provides many options to help you debug and adjust your program:

- Cross-Reference browser
- Animation tables
- Forcing I/Os
- Program animation

UNINTENDED EQUIPMENT OPERATION

Only qualified personnel with knowledge of the control system logic and its effect on the machine or process should execute Controller Operations, Online Programming, Forcing and/or other changes to the controller's memory.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

Cross-Referencing your Program

Introduction

Cross referencing makes it easier to locate several occurrences of the same program element through out the application, for debugging purposes.

It consists of selecting items in a program such as an address that you want to track in an application. Once the items are selected, then a list is generated displaying where the items are used in the application. Cross referencing provides a useful list of the operands, symbols, lines and operators used in all or part of an application.

Cross-Reference Browser

Select Program

 \rightarrow Program $\dashv \vdash^{\bullet}$

on the TwidoSuite Steps bar.

Click **Cross-Ref browser** on the functions bar to display the cross-reference browser. The cross-reference browser displays to the right of the program window.

Operand: % Symbol: TE	10.0.0 ST	Configure
Section	Location	Operator
Section 1	Rung 1	$\dashv \vdash$
Section 1	Rung 1	- / -

How to Cross-Reference your Application

This is a simple four-step procedure:

- 1. Click the specific program item you want to cross-reference. **Result:** The cross-reference table is updated.
- If you want to change the configuration settings of the cross-referenced object, click the **Configure** shortcut in the Cross-Reference browser.
 Result: This brings up the hardware or software object configuration screen with the cursor pointing on the cross-referenced object.
- **3.** Configure the desired object in the hardware or software object configuration table.
- 4. Click the 🗇 button to return to the Cross-Reference browser.

Using Animation Tables

Use an animation table to view and adjust program variables **online**, when the PLC is either in Run or Stop mode.

With an animation table, you can

- as the program is running, monitor the actual value of any variable in the controller and compare against expected value,
- change the value of variables independent of calculated values, until they are updated again,
- backup the current values of all variables in an animation table,
- restore to the controller the retained values of all variables in an animation table,
- force inputs and outputs.

DANGER

UNINTENDED EQUIPMENT OPERATION

You must understand the program logic and the frequency in which a variable's value may change in order to correctly interpret the displayed value

Failure to follow these instructions will result in death or serious injury.



Elements of an Animation Table

For more details, please refer to *Debugging Online via the Program Animation* in *TwidoSuite Operation Guide - Online Help.*

Forcing I/Os

WARNING

UNEXPECTED EQUIPMENT OPERATION

You must have prior knowledge of the process and the controlled equipment before attempting to force inputs and/or outputs on or off.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

Forcing input and output values in a running controller can have serious consequences to the operation of a machine or process. Only those who understand the implications in the controlling logic, and who understand the consequences of forced I/O on the machine or process, should attempt to use this function.

Forcing I/Os means that you forcibly set the values of one or more input or output bits to either 0 or 1.

NOTE: You can force I/Os when TwidoSuite is in **online** mode, with the controller either in Run or Stop mode.

How to Force I/Os in an Animation Table

The animation table tool bar provides Force Commands:

- 1 Force to 1
- Force to 0
- Clear Force
- Clear All Force

To force a value to 0 or 1, or clear a forced value:

- **1.** Highlight a variable in the animation table.
- 2. Click the desired Force to 0, Force to 1 or Clear Force command on the animation table tool bar.

Result: In the column labeled **Current** in the animation table, the forced variable displays with a "F" prefix paired with the forced state "0" or "1": "F 0" or "F 1".

Animating a Program

You can animate both Ladder and List programs when online. This section describes how to animate a Ladder language program. For more details, please refer to *Animating a Program* in *TwidoSuite Operation Guide - Online Help.*

WARNING

UNINTENDED EQUIPMENT OPERATION

Only qualified personnel with knowledge of the control system logic and its effect on the machine or process should execute Controller Operations, Online Programming, Forcing and/or other changes to the controller's memory.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

How to Animate a Ladder Program

1. Select the **Program** → **Debug** → **Animate program** task to open the program editor in animated mode.

Result: The program editor displays animated ladder elements.

2. Watch the animated ladder elements during program execution.

How Ladder Animation Works

- You can watch the backlight of logical objects such as contacts, coils and special objects turn on as their logical value becomes 1.
- You can keep track of data variables of function blocks, comparison blocks and operation blocks, including current and preset values.

NOTE: Binary operands are displayed as 0 or 1, while all other values are displayed in hexadecimal or decimal, depending on the format selected in the HEX/DEC button in the toolbar.

Display/hide the Animation tables

Click the icon in the functions bar to display/hide the Animation tables in the lower part of the window.

Copying Rung Objects to an Animation Table

To copy rung objects to the selected animation table, press (leftmost button on the animation table's tool bar) as shown in the figure below.

					🖉 🛞 Telemecanique	
Project Desc	cribe Program Rep	P /	<u></u>		My project	Stop 👀
			Configure	Program	Debug	
Ladder 💌 🖶 🖧 🏝	S 100% ▼ S []	°a ₽ ₽ ₩		1		Disconnect
₩ 5. 5. 1. 1/	+)+) \□ ₩	[]- []- %™ %C -	≫ •	▶ +1-+/⊦	4PF 4NF	Animate the program
1 LD						Manage animation tables
Rung 0						Check PLC
	7					Monitor hardware
%10.3						configuration Monitor
HH						software configuration
					<u>.</u>	described
🌐 🚽 🗙 🐅 🦛 🗧	e 2 °2 '2 4	My animation tal	ole 1 💌			Monitor the behavior
Addres	ss Symbol	Gurrent	Retained	Format		
1 🗖 %M0			0	Decimal		
2 🔽 🔽 %Q0.1		0	0	Decimal		
з 🔽 %Ю.О		0	0	Decimal		
4						
- EXECUTION WARNING -: NO S	START IN RUN WAS		00			
		(a) Taintain				

Step 9: Manage the Program Report

Introduction

With TwidoSuite report, you create custom printouts and html exports (to .htm file) by selecting report items from the report manager browser.

Report Manager

Use the report manager to select report components, configure printing options, and export the application report to HTML format.

To access the Report Manager window, select the **Report** icon TwidoSuite Steps bar.

on the

How to Configure the Report

The report manager provides a tree-like structure view of the report items and subitems that can be included in the report by checking the appropriate boxes.



To configure the report, select an item from the report browser and set the options that appear in the configuration window. For details on report options, please refer to the *TwidoSuite Operation Guide - Online Help.*

Page Setup

Select the **Report** \rightarrow **Page Setup** task to set the information you want to display in page headers and footers, and the page margins as well.

You can configure your report pages to show up to nine different types of information in three seperate fields per header and footer line, including:

You can configure in your report page to show up to three different type of information in three seperate fields per header and footer, including:

- Print date
- Creation date
- Modification date
- Project name
- Any text (Free)
- No text (None)
- Page number/Total number of pages (Page i/n)
- Page number (Page i)
- TwidoSuite version
- File name

Print the Report

Select the **Report** \rightarrow **Print** task to prepare the report for sending to the printer and/or to an HTML export file.

The print window allows you to:

- preview the report with several page format and zooming options,
- choose the destination printer and access the printer properties,
- repaginate your report according to selected printing options
- send your report for printing on the selected print device,
- export your report to a HTML file.
Monitoring an Application

Monitoring an Application

How to Start the Monitoring Utility

To start the TwidoSuite Monitoring Utility:

1. Open the Application Launcher by clicking the icon located on your PC desktop.



TwidoSuite

Result: The Application Launcher dialog box appears as shown below.

2. From TwidoSuite Application Launcher, click Monitoring Mode

6

Monitoring Features

From within Monitoring Mode, select Check PLC:

See memory information Adjust RTC-Time Controller Status See Ethernet Statistics Modify modem Configuration Potentiometer adjustment point 0 Potentiometer adjustment point 1 Sea Ethernet Statistics Modify modem configuration Potentiometer adjustment point 0 Potentiometer adjustment point 1 Scan Time Maximum (ms) Current (ms) Minimum (ms) Substitute for the controller with the confi- guration defined by the application. Modem: Image: Im	Select a task	
Modify modem configuration Maximum (ms) The configuration that you will enter will be substitued for the conficient with the configuration. Maximum (ms) Modern: ID-33/450 Modern: ID-33/450 Atteool&B18/D0&H0&I0&R Image: Controller Real Time Clock Date (dd/mm/yy) Time (th::mm:ss) Reset Hayes Command: Image: Controller Real Time Clock Modern: Image: Controller Real Time Clock Date (dd/mm/yy) Time (th::mm:ss) Name Image: Controller Real Time Clock	See memory information Adjust RTC Time Configure Real Time Clock See Ethernet Statistics Modify modem Configuration	Controller Status
Modify modem configuration Maximum (ms) Current (ms) Minimum (ms) The configuration that you will enter will be substitued for the controller with the configuration. Minimum (ms) Minimum (ms) guration defined by the application. Modem: The configuration that the configuration (ms) Controller Real Time Clock Modem: TD:33/v80 Controller Real Time Clock Date (dd/mm//yy) Reset Hayes Command: Date (dd/mm//yy) Time (hir.mm:ss) RTG Correction Modem connected Maxe		Scan Time
Reset Hayes Command: Date (dd/rm/yy) Time (hh:mm:ss) RTG Correction ATEOQ1&B1&00&H0&I0&R Image: Constraint of the connected Name Image: Constraint of the connected Name Image: Constraint of the connected Name	Modify modem configuration The configuration that you will enter will be substitued for the controller with the configuration defined by the application. Modern: TD-33/V90	Maximum (ms) Current (ms) Minimum (ms) Watchdog time out Controller Real Time Clock
Apply Cancel	Reset Hayes Command: ATEOO1&B1&DO&HO&IO&R 1&SOSO Apply Cancel	Date (dd/mm/yy) Time (hh:mm:ss) RTG Correction Modem connected

The Monitoring Utility allows you to perform the following tasks:

- 1. See memory information
- 2. Adjust RTC time
- 3. Configure RTC (Real Time Clock) Correction factor
- 4. See Ethernet statistics
- 5. Modify modem configuration

WARNING

UNINTENDED EQUIPMENT OPERATION

Only qualified personnel with knowledge of the control system logic and its effect on the machine or process should execute Controller Operations, Online Programming, Forcing and/or other changes to the controller's memory.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

For details on how to use the various monitoring features, please refer to *Hardware Monitoring* chapter in *TwidoSuite Operation Guide - Online help.*

For details on the various parameters, refer to Check PLC.

Index



Ε

Executive Loader Wizard, 15, 15

F

Firmware Executive Update, 15

Η

hardware installation requirements, 10

I

installation requirements, *10* installing the software, *11*

Ρ

Preferences, 22

R

removing the software, 11

S

software installation requirements, 10 start program, 13

U

uninstalling the software, 11