

CERTIFICATE OF COMPLIANCE

Certificate Number 20160201-E350924
Report Reference E350924-20120725
Issue Date 2016-FEBRUARY-01

Issued to: SCHNEIDER ELECTRIC USA INC
SCHNEIDER ELECTRIC
SURGE PROTECTION BUSINESS
1751 S 4800 W
SALT LAKE CITY UT 84104

**This is to certify that
representative samples of**

CIRCUIT BREAKERS AND SURGE-PROTECTIVE
DEVICES

See addendum page for models

Have been investigated by UL in accordance with the
Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL 1449 - Surge Protective Devices
CSA-C233.1-87 - Gapless Metal Oxide Surge Arresters for
Alternating Current Systems"

Additional Information:

See the UL Online Certifications Directory at
www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20160201-E350924
Report Reference E350924-20120725
Issue Date 2016-FEBRUARY-01

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

USL/CNL - Circuit Breaker and Surge Protective Devices, Type 1 SPD, Models:

HR1IMA12, HR1IMA16, HR1IMA24, HR2IMA12, HR2IMA16, HR2IMA24, HR3IMA12, HR3IMA16, HR3IMA24, HR4IMA12, HR4IMA16, HR4IMA24, HR8IMA12, HR8IMA16, HR8IMA24, HR5IMA10C, HR5IMA12C, HR5IMA16C, HR5IMA20C, HR5IMA24C, HR6IMA10C, HR6IMA12C, HR6IMA16C, HR6IMA20C, HR6IMA24C, HR9IMA10C, HR9IMA12C, HR9IMA16C, HR9IMA18C, HR5IMA10C1, HR5IMA12C1, HR5IMA16C1, HR5IMA20C1, HR5IMA24C1, HR6IMA10C1, HR6IMA12C1, HR6IMA16C1, HR6IMA20C1, HR6IMA24C1, HR9IMA10C1, HR9IMA12C1, HR9IMA16C1, HR9IMA18C1, HR4HIMA10C, HR4HIMA12C, HR4HIMA16C, HR4HIMA20C, HR4HIMA24C, HR8HIMA10C, HR8HIMA12C, HR8HIMA16C, HR8HIMA18C, HR4HIMA10C1, HR4HIMA12C1, HR4HIMA16C1, HR4HIMA20C1, HR4HIMA24C1, HR8HIMA10C1, HR8HIMA12C1, HR8HIMA16C1, HR8HIMA18C1, HL1IMA12, HL1IMA16, HL1IMA24, HL2IMA12, HL2IMA16, HL2IMA24, HL3IMA12, HL3IMA16, HL3IMA24, HL4IMA12, HL4IMA16, HL4IMA24, HL5IMA10C, HL5IMA12C, HL5IMA16C, HL5IMA20C, HL5IMA24C, HL6IMA10C, HL6IMA12C, HL6IMA16C, HL6IMA20C, HL6IMA24C, HL5IMA10C1, HL5IMA12C1, HL5IMA16C1, HL5IMA20C1, HL5IMA24C1, HL6IMA10C1, HL6IMA12C1, HL6IMA16C1, HL6IMA20C1, HL6IMA24C1, HL4HIMA10C, HL4HIMA12C, HL4HIMA16C, HL4HIMA20C, HL4HIMA24C, HL8HIMA10C, HL8HIMA12C, HL8HIMA16C, HL8HIMA18C, HL4HIMA10C1, HL4HIMA12C1, HL4HIMA16C1, HL4HIMA20C1, HL4HIMA24C1, HL8HIMA10C1, HL8HIMA12C1, HL8HIMA16C1 and HL8HIMA18C1



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/about/locations/>

