

Certificate of Compliance

Certificate Number(s):

UL-US-2446428-6

Report Reference:

E486184-20241205

Issue Date:

2025-08-22

Issued to:

**SCHNEIDER ELECTRIC FRANCE, DBA Industrial Automation
35 rue Joseph Monier, Rueil Malmaison, 92500, FR**

This certificate confirms that representative samples of:

NRAQ - Programmable Controllers

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

UL 61010-1, 3rd Ed., Issue Date: 2012-05-11, Revision Date: 2023-06-06

UL 61010-2-201, Edition 2, Issue Date 2018-05-14, Revision Date 2022-08-08

Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



David Piecuch
UL Mark Certification Program Manager



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

CERTIFICATE OF COMPLIANCE

Certificate number(s): UL-US-2446428-6
Report reference: E486184-20241205
Issue Date: 2025-08-22

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Programmable Controllers

Model(s): Modicon Edge I/O NTS System, : NTSFMB0120(K), NTSPCM1600H(K), NTSDDO0602(K), NTSAHIO412XH(K), NTSDAO0415(K), NTSDRC0415(K), NTSEHC0120H(K), NTSDDI0402(K), NTSART0214H(K), NTSNEC1200H(K), NTSAMO0400(K), NTSART0214(K), NTSAHO0212H(K), NTSAMO0210H(K), NTSAMI0800(K), NTSEME0102(K), NTSEDM0822(K), NTSPFB1002H(K), NTSDDO0802(K), NTSDMY0200H(K), NTSDAO0205(K), NTSDDO0802X(K), NTSEDO0810(K), NTSFMB0120H(K), NTSXBA0301H, NTSDDO0402(K), NTSPCM0808H(K), NTSDDO1602XA(K), NTSDDO0402H(K), NTSDDI0602(K), NTSXBA0103H, NTSXBA0201H, NTSDDO1602X(K), NTSEHE0221(K), NTSDDI0402H(K), NTSAMM0600(K), NTSART0404XH(K), NTSXBA0100H, NTSPFD1002H(K), NTSACI0802X(K), NTSDDI1602X(K), NTSDDI1602XH(K), NTSXBA0213H, NTSEME0101(K), NTSXBA0104H, NTSAMI0210(K), NTSEDT0810(K), NTSDDO0212H(K), NTSDAI0804(K), NTSEHC0220(K), NTSAMI0210H(K), NTSPCM0016H(K), NTSDAI0215H(K), NTSEHC0100(K), NTSXBA0200H, NTSEMP0220(K), NTSAMO0400H(K), NTSDDO1602(K), NTSART0404(K), NTSEDT0800(K), NTSNEC1200(K), NTSDAI0403H(K), NTSDDI1602(K), NTSDRC0415H(K), NTSART0603(K), NTSDAO0415H(K), NTSDDO1602XAH(K), NTSXMP0000H(K), NTSDRA0615(K), NTSAMI0400(K), NTSDRC0215(K), NTSDMY0100H(K), NTSXBA0214H, NTSAMI0420(K), NTSNSC1200(K), NTSEME0110(K), NTSDDI0802X(K), NTSDDO1602XH(K), NTSDDI1642(K), NTSECS0121(K), NTSDAI0404H(K), NTSAMO0210(K), NTSACI0802XH(K), NTSFIO0400(K)



David Piecuch
UL Mark Certification Program Manager

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.



Certificate of Compliance

Certificate Number(s):

UL-CA-2435085-6

Report Reference:

E486184-20241205

Issue Date:

2025-08-22

Issued to:

**SCHNEIDER ELECTRIC FRANCE, DBA Industrial Automation
35 rue Joseph Monier, Rueil Malmaison, 92500, FR**

This certificate confirms that representative samples of:

NRAQ7 - Programmable Controllers Certified for Canada

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

**CSA C22.2 No. 61010-2-201:18, 2nd Ed., Issue Date: 2018-02-01
CAN/CSA-C22.2 No. 61010-1-12, Edition 3, Issue Date 2012-05-11, Revision Date 2023-06**

Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



David Piecuch
UL Mark Certification Program Manager



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

CERTIFICATE OF COMPLIANCE

Certificate number(s): UL-CA-2435085-6
Report reference: E486184-20241205
Issue Date: 2025-08-22

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Programmable Controllers

Model(s): Modicon Edge I/O NTS System, : NTSFMB0120(K), NTSPCM1600H(K), NTSDDO0602(K), NTSAGI0412XH(K), NTSDAO0415(K), NTSDRC0415(K), NTSEHC0120H(K), NTSDDI0402(K), NTSART0214H(K), NTSNEC1200H(K), NTSAMO0400(K), NTSART0214(K), NTSAGO0212H(K), NTSAMO0210H(K), NTSAMI0800(K), NTSEME0102(K), NTSEDM0822(K), NTSPFB1002H(K), NTSDDO0802(K), NTSDMY0200H(K), NTSDAO0205(K), NTSDDO0802X(K), NTSEDO0810(K), NTSFMB0120H(K), NTSXBA0301H, NTSDDO0402(K), NTSPCM0808H(K), NTSDDO1602XA(K), NTSDDO0402H(K), NTSDDI0602(K), NTSXBA0103H, NTSXBA0201H, NTSDDO1602X(K), NTSEHE0221(K), NTSDDI0402H(K), NTSAMM0600(K), NTSART0404XH(K), NTSXBA0100H, NTSPFD1002H(K), NTSACI0802X(K), NTSDDI1602X(K), NTSDDI1602XH(K), NTSXBA0213H, NTSEME0101(K), NTSXBA0104H, NTSAMI0210(K), NTSEDT0810(K), NTSDDO0212H(K), NTSDAI0804(K), NTSEHC0220(K), NTSAMI0210H(K), NTSPCM0016H(K), NTSDAI0215H(K), NTSEHC0100(K), NTSXBA0200H, NTSEMP0220(K), NTSAMO0400H(K), NTSDDO1602(K), NTSART0404(K), NTSEDT0800(K), NTSNEC1200(K), NTSDAI0403H(K), NTSDDI1602(K), NTSDRC0415H(K), NTSART0603(K), NTSDAO0415H(K), NTSDDO1602XAH(K), NTSXMP0000H(K), NTSDRA0615(K), NTSAMI0400(K), NTSDRC0215(K), NTSDMY0100H(K), NTSXBA0214H, NTSAMI0420(K), NTSNSC1200(K), NTSEME0110(K), NTSDDI0802X(K), NTSDDO1602XH(K), NTSDDI1642(K), NTSECS0121(K), NTSDAI0404H(K), NTSAMO0210(K), NTSACI0802XH(K), NTSFIO0400(K)



David Piecuch
UL Mark Certification Program Manager

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

