


⚠ ⚠ DANGER / 危险
HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH
 Disconnect all power before servicing equipment.
 Failure to follow these instructions will result in death or serious injury.
 可能有触电、爆炸或电弧灼伤危险
 在此电力设备上进行操作时，请先断开所有电源。
 不遵循上述规定将可能导致人员伤亡。

GV2LE, GV2RT
 S1B19868-01
 10 - 2012

www.schneider-electric.com



| | |
|--|--|
| | 1...6 mm ² AWG 18...10 |
| | 1,5...6 mm ² AWG 16...10 |
| | 1...4 mm ² AWG 18...12 |
| | 1,7 N.m 15 lb-in |
| | Ø 4 mm 0.16 in. |