










W913808740121



⚠ DANGER
HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH
 Disconnect all power before servicing equipment.
 Failure to follow these instructions will result in death or serious injury.



Ø 3 mm Ø 0.118 in.				Ø 3 mm Ø 0.118 in.				
1, ...2,	1, ...4	1, ...6,	0, ...1,	0, ...2,	1, ...2,	0,34 ...1	0, ...1,	
A C			10 - 3		A 60 14 - 1 C		1 - 20 C	
TR 3			TR 3		TR 3		TR 3	