

CERTIFICATE OF COMPLIANCE

Certificate Number 20180406-E164353
Report Reference E39281-19930202
Issue Date 2018-APRIL-06

Issued to: Schneider Electric Industries S A, DBA Telemecanique
8001 Knightdale Blvd
Knightdale NC 27545

**This is to certify that
representative samples of**

AUXILIARY DEVICES

Thermal overload relays type LR2K followed by -0301, -0302, -0303, -0304, -0305, -0306, -0307, -0308, -0310, -0312, -0314, -0316. Adapter LA7K0064.

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety:

UL 60947-1 & CSA C22.2 No. 60947-1, Low-Voltage Switchgear and Controlgear – PART 1: General Rules
UL 60947-4-1 & CSA C22.2 No. 60947-4-1, Low-Voltage Switchgear and Controlgear – Part 4-1: Contactors and Motor-Starters — Electromechanical Contactors and Motor-Starters

Additional Information:

See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

