Milwaukee

14-46-0234

Service Instruction Notice

Intermediate Pinion Kit - Magnum® Drill or Hammer-Drill

Woodruff keys and corresponding keyways are being removed from all of the gear stages of the specified Magnum® Drills and Magnum® Hammer-Drills listed below. The old (keyed) components are no longer available and are replaced by a new service kit / service replacement part.

Locate the model number and serial number range of the tool to be serviced below; ordering the Replacement Kit /Part as indicated.

Model / Catalog No.	Serial Number Range affected	Obsolete Part(s) (remove & discard)	Replacement Kit / Part
0234-1	532-140000 thru 532-14440979 532A, 532B	32-40-1815 Intermediate Gear 36-66-4260 Intermediate Pinion 06-42-0400 Woodruff Key	36-66-0234 Intermediate Pinion Kit
0234-75 0235-1	987A 755-1001 thru 755-151735		
0236-3	755A, 755B 577-1011 thru 577-1653		
0235-20 0235-21	978A 056A	32-40-1815 Intermediate Gear 36-66-4285 Intermediate Pinion 06-42-0400 Woodruff Key	36-66-0235 Intermediate Pinion Kit
0244-1	664-1001 thru 664-1311195	32-40-1815 Intermediate Gear 36-66-4290 Intermediate Pinion 06-42-0400 Woodruff Key	36-66-0244 Intermediate Pinion Kit
5370-1 5371-20 5376-1	672-1001 thru 672-344966 672A, 672B, 672C, 672D 408A, 408B 819-1001 thru 819-39199 819A, 819B, 819C, 819D	32-40-1815 Intermediate Gear	32-40-1816 Intermediate Gear

A local Milwaukee *authorized* Service Station or *factory* Service/Sales Support Branch can help with the purchase of the correct Replacement Kit / Replacement Part. To locate the *authorized* Service Station or *factory* Service/Sales Support Branch nearest you call 1.800.SAWDUST (1.800.729.3878) or visit www.milwaukeetool.com - a complete searchable database for these locations is found under the 'Part & Service' - 'Service Center Search' icon / section

Replacement Kit / Replacement Part can also be purchased by calling and talking with our Global Customer Service personnel at 1.800.SAWDUST [1.800.729.3878], select prompt #1, Monday – Friday, 6:00AM – 6:30PM, Central Time. Service replacement parts orders will be shipped COD or we accept most major credit cards for payment. A \$5.00 charge will be added to orders having a billing value under \$30.00.