CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L33139-42751-01016102-5

Report Reference E33139-20161010

Date 6-Dec-2023

Issued to: Schneider Electric USA Inc

330 Weakley Ln Smyrna, TN 37167 United States

This is to certify that representative samples of

QEUY2 - Panelboard and Switchboard Accessories -

Component

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the component requirements in the Standard(s) indicated on this Certificate. UL Recognized components are incomplete in certain constructional features or restricted in

performance capabilities and are intended for installation in complete equipment submitted for investigation to UL LLC.

Standard(s) for Safety: UL 67, Edition 13, Issue Date 2018-05-15, Revision Date

2023-08-22

Additional Information: See the UL Online Certifications Directory at

https://ig.ulprospector.com for additional information

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Recognized Component Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Recognized Component Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Recognized Component Mark on the product.

Deborah Jennings-Conner, VP Regulatory Services

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at http://ul.com/aboutul/locations/



CERTIFICATE OF COMPLIANCE

Certificate Number UL-US-L33139-42751-01016102-5

Report Reference E33139-20161010

Date 6-Dec-2023

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Model	Category Description
HJQLLC	Service entrance kits
ILBFMHCJHJULC	Service entrance barrier kits
ILBFMHCPHJULC	Service entrance barrier kits
ILBFMHCPLULC	Service entrance barrier kits
ILBFMHCPMPULC	Service entrance barrier kits
ILBFMHCRLULC	Service entrance barrier kits
ILBFMHCRMULC	Service entrance barrier kits
ILBFMHCRPULC	Service entrance barrier kits
ILBFMHCRRULC	Service entrance barrier kits
ILCOMBLUL26W	Service entrance barrier kits
ILCOMBLUL32W	Service entrance barrier kits
ILCOMBLUL44W	Service entrance barrier kits
ILCOMBMPUL26W	Service entrance barrier kits
ILCOMBMPUL32W	Service entrance barrier kits
ILCOMBMPUL44W	Service entrance barrier kits
ILLALLC	Service entrance kits
ILMLC2W	Service entrance kits
ILMLC3W	Service entrance kits
ILMLC4W	Service entrance kits
ILPPLLC	Service entrance kits
LALLC	Service entrance kits
NFEDBS	Service entrance kits
NFHJLLC	Service entrance kits
NFLALLC	Service entrance kits
NFPPLLLC	Panelboards
NFPPPLLC	Panelboards
NQHJQLLC	Service entrance kits
NQLALLC	Service entrance kits
NQPPLLLC	Service entrance kits
PPLLC	Service entrance kits
QMBFSLC6	Service entrance barrier kits
QMBFSLC8	Service entrance barrier kits

Deborah Jennings-Conner VP Regulatory Service

UL LLC

kny miorinarion and documentation involving du lara is ervices are provided on behalf of ductor (ductor) of any authorized incrisee of ductor (duestions, please contact a local UL Customer Service Representative at https://di.com/aboutul/locations/

(U)