

CERTIFICATE OF COMPLIANCE

Certificate Number 20190131-EV33981
Report Reference EV33981-20190127
Issue Date 2019-JANUARY-31

Issued to: APPLETON GROUP
9377 W HIGGINS RD
ROSEMONT IL 60018

**This certificate confirms that
representative samples of**

TRANSFORMERS, DISTRIBUTION, DRY AND LIQUID-FILLED TYPES CERTIFIED FOR ENERGY EFFICIENCY
Dry-type Power transformers, Energy Efficiency models
E2H15S, E2H30S, E2H45S, E2H75S, E2H150S, E5H15S,
E5H30S, E5H45S, E5H75S, E5H112S, E7H15S, E7H30S,
E7H45S, E7H75S, E71H15S, E71H30S, E71H45S,
E71H75S, E71H112S, E79H15S, E79H30S, E79H45S,
ES5H15S, ES5H37S, ES5H50S, ES5H100S.

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.


Standard(s) for Safety: CSA C802.2-12, Minimum Efficiency Values for Dry-Type Transformers.

Additional Information: See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

